



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.



#### FEL-PRO INSTALLATION TIPS

Requires Crankshaft Machining due to Clearance Issues. The Crankshaft Seal Surface Must be machined down to an OD of 3.833" to accept the Repair Sleeve.

The Sleeve will restore the OD of the crankshaft to its original diameter.

© 2007 Federal-Mogul Corporation  
Form No. I-2085 (Rev. 1/09)

Printed in U.S.A.