

W A R N I N G !

To ensure that correct head gasket is installed on the 1999 SUBARU 2.5L DOHC (EJ25D) engine.

Measure the thickness of the OEM head gasket removed from the engine.

Use of the wrong gasket thickness will cause a piston to cylinder head clearance problem.

- If the gasket measures approximately .026" thick use Fel-Pro head gasket 26415 PT.
- If gasket measures approximately .053" thick use Fel-Pro head gasket 26167 PT.