



ATTENTION: Refer to the appropriate shop manual for your vehicle to obtain specific service procedures for this part. If you do not have a service manual or lack the skill to install this part, it is recommended that you seek the services of a qualified technician. Pay special attention to all cautions and warnings included in the shop manual. Read and follow all instructions carefully.

Nissan Armada, Titan 2004–12, Nissan Quest 2004–09, Infiniti QX56 2004–11

Reset Procedure

1. Unbolt the window regulator from the door and disconnect the wiring harness from the window lift motor.
2. Remove window regulator assembly.
3. Unbolt the window lift motor from the window regulator.
4. With the window lift motor disconnected from the window regulator, reconnect the window lift motor to the wiring harness.
5. With the window lift motor connected to the wiring harness, using the switch **MANUALLY** hold the window switch in the up position for 5 seconds.
(**NOTE:** Do not pull the switch fully back this will cause the auto-up feature to kick in, which will result in the internal limit switch not fully being activated.)
6. Reinstall the motor onto the window regulator and reinstall the window regulator assembly.

Disclaimer:

Even though every attempt is made to ensure this information is complete and accurate, it is impossible to account for all possible circumstances or situations. Please consult with a qualified auto technician before attempting to perform any work you are not qualified to do. Automobiles can be hazardous to work on; be sure to take all necessary safety precautions. Failure to do so may result in property damage or personal injury. Certain motor vehicle standards and performance requirements may apply to your motor vehicle (such as Federal Motor Vehicle Safety Standards by the National Highway Traffic Safety Administration). Be sure that your work is performed in accordance with such standards and that you do not disable any motor vehicle safety feature.