

COMPONENT ALERT



Shims Are No Longer Included

IMPORTANT: The new tensioner is no longer supplied with shims. Reuse the original shim, there is no need to replace them.

ContiTech Timing Belt Kits
TB285K2
TB285K3







New Tensioner 4771085

CA-004 Rev 0

CRP Industries Inc. 35 Commerce Drive Cranbury, NJ 08512 USA 609-578-4100 800-526-4066

DISCLAIMER: While every effort has been made to substantiate the information contained in this Component Alert, CRP Industries Inc. will not warrant its accuracy or completeness. CRP Industries Inc. assumes no responsibility for any loss, injury, damage, or expense directly or indirectly due to errors or omissions or arising out of or relating to use or reliance on the information contained herein. The information contained herein is not intended to replace manufacturer's operating or safety instructions and is subject to change without notice. To obtain the most current data, please refer to the latest recommendations from the appropriate manufacturer.